

# New Automated Spray System Helps Confectionary Manufacturer Solve Clogging Problem and Increase Production by 78%




## Problem:

The Shanghai branch of Lotte Food coats almonds, hazelnuts and raisins with chocolate to create delicious treats. The coating takes place in a cylindrical tumbler. Compressed air was used to blow chocolate that was dripping from nozzles on to the nuts and raisins. This process was very slow – approximately eight hours were needed to coat and cool treats. Plus, the use of large drops and inefficient temperature control resulted in clogged nozzles and unscheduled downtime for maintenance.

## Solution:

The Spraying Systems Co. solution was an AccuCoat® Pan Spraying System with a heated 63600 spray manifold. An AutoJet® Model 2250 Spray Controller monitors and automatically adjusts system components in the fully-jacketed system to ensure proper chocolate viscosity is maintained. The spray controller also facilitates quick production changeover by storing recipes for various products.

The spray manifold is equipped with ten air atomizing nozzles with clean-out needles to prevent clogging.





## New Automated Spray System Helps Confectionary Manufacturer Solve Clogging Problem and Increase Production by 78% – Continued

### Results:

The AccuCoat® Pan Spraying System has solved Lotte's coating problems. Chocolate temperature is precisely controlled, clogging has been eliminated and batch changeover is quick. Lotte's production of chocolate coated treats has increased by 78%. The equipment cost was recouped in just over one week. Lotte no longer plans to purchase additional equipment to meet its production goals since the single AccuCoat system has proven so effective.

### A CLOSER LOOK AT THE SYSTEM



The **63600 spray manifold** provides superior performance with viscous coatings. The large diameter liquid passage helps to ensure consistent flow and minimize pressure drop while the hot water jacket improves flow and maintains a consistent temperature up to the nozzle orifice. The 63600 spray manifold also has a sanitary design to reduce the risk of contamination.



The **1/4JAU nozzles** feature a clean-out needle which slides through the liquid orifice to clear obstructions and prevent clogging.



The **AccuCoat Pan Spraying System** consists of an AutoJet® Model 2250 Spray Controller and a 63600 spray manifold with ten 1/4JAU air atomizing nozzles. The fully-jacketed system provides closed-loop temperature control to maintain the proper chocolate viscosity.



**Spraying Systems Co.®**  
Experts in Spray Technology

North Avenue and Schmale Road, P.O. Box 7900, Wheaton, IL 60187-7901 USA

Tel: 1.800.95.SPRAY    Intl. Tel: 1.630.665.5000  
Fax: 1.888.95.SPRAY    Intl. Fax: 1.630.260.0842  
www.spray.com



Case Study No. 183    ©Spraying Systems Co. 2014